

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD		Amendment Design Review (ADR) Yes/No: <u>Yes</u>	ECN #: <u>840</u>
Date: <u>06.08.09</u>		ADR Date: <u>06.08.10</u>	
Job No:		Created By: <u>PH</u>	Checked By:
Product No: <u>D206-667</u>		Approved By:	Approved By:
Product Name: <u>Cross-tube installation</u>		(Proj. Manager)	(Management if reqd)

Documents Affected:

RELEASE : DSI 9346, Rev A

#	Engineering Actions	Yes	No	Responsible	To happen by:	Complete
1	Required Documents/Drawings Under Review?	✓		PH	ASAP	06.08.10 PH
2	Update Blue/Pink Folder/Electronic File		✓			
3	Update DSI Folder Electronic File	✓		KJ	06.08.25	06.08.23 KJ
4	Update D-Part Master Binder		✓			
5	Update Grey Project Binder	✓		PH/KJ	06.08.11	06.08.23 KJ
6	Update DEO/DSI Binder	✓		KJ	06.08.25	06.08.23 KJ
7	Update Master Document List (MDL)		✓			
8	Update Document Record (DR)	✓		KJ	06.08.25	06.08.22 KJ
9	Update Change Record Form		✓			
10	Move Electronic File	✓		KJ	06.08.25	06.08.23 KJ
11	Notify TC of Change		✓			
12	Notify FAA of Change		✓			
13	Update QSI 021 (TC/FAA STC)		✓			
14	Update QSI 036 (K-Kits)		✓			
15	Update Accpac Database		✓			
16	Update Access Database		✓			
17	Verification ARC		✓			
18	Update STC Approval List		✓			
19	Update Product Development Summary		✓			
20	Create/Update COSS (Estimate/BOM)		✓			
21	Create/Update PPP's		✓			
22	Update Paperwork Kits in Production	✓		LL/PH	06.08.11	06.12.04 PH
23	Update Paperwork Kits in Stock	✓		LL/PH	06.08.11	
24	Red Tag Stock with old CHG #		✓			
25	Rework/Scrap Current Production	✓		LL	06.08.11	U 06.11.28
26	Rework/Scrap Kits in Stock?	✓		LL	06.08.11	
27	Update Qpulse/Laminated Dwgs		✓			
28	Create/Update Controlled PDF Files		✓			
29	Create/Update FAI sheets		✓			
30	Create/Update CNC Programs		✓			
31	Create/Update Tooling	✓		JLM/EC	ASAP	EC 02.09.4
32	MPP required?		✓			
33	Notify Previous Customers		✓			
34	Notify Eurocopter France		✓			
35						
36						

Description / Action:

- REFERENCE NCR #071
- RE-WORK IN STOCK/IN PRODUCTION AND ATTACH DSI 9346 TO KIT
- RE-WORK TOOLING IN ORDER TO HAVE HOLES DRILLED IN CORRECT LOCATION
- THIS DSI/RE-WORK WILL AFFECT X-TUBES WITH HOLES DRILLED INCORRECTLY
- DO NOT ADD TO BLUE/PINK FILE

ECN Complete: MP

Date: 9/1/07